

	FAN COIL UNIT						
Sty	Brand	No.	Model	No.	Model	Location	Remarks
1st	Daikin						
		VFCU 1-1A	FXYM200			Meeting Room 1A	
		VFCU 1-1B	FXYM63			Meeting Room 1B	
		VFCU 1-1C	FXYM63			Training Room 1C	
		VFCU 1-2A	FXYM200			Meeting Room 1D	
		VFCU 1-2B	FXYM50			Courtyard Area	
		VFCU 1-3A	FXYM125			IT	
		VFCU 1-3B	FXYM100			Meeting Room 1A	
		VFCU 1-4	FXYM200			Courtyard Area	
		VFCU 1-5	FXYM200			Reception Area	
		VFCU 1-6	FXYM250			Reception Area	
		VFCU 1-7	FXYM250			Entrance Lobby	
		FCU 1-9	FT35			FCC Room	
2nd	Daikin						
			FT45			MDF Room	
		FCU 1-1	FXFQ125AVM			Server room	
		FCU 1-2	FXFQ125AVM			Server room	CU-1 (RXMQ9AY1)
		FCU 1-3	FXFQ25AVM			Equipment room	
		FCU 2-1	FXFQ125AVM			Server room	
		FCU 2-2	FXFQ125AVM			Server room	CU-2 (RXMQ9AY1)
		FCU 2-3	FXFQ25AVM			Storage of painting room	
		VFCU 2-3D	FXYA25			Pantry (Cleaner Store)	
		VCU 2-4A & 2-4B	FXYF80 x 2			Training Suite 2B	
		VFCU 2-4C	FXYM80			Corridor	
		VCU 2-5A & 2-5B	FXYF80 x 2			Training Suite 2A	
		VFCU 2-5C	FXYM80			Lift Lobby	
		VCU 2-6 to 2-9	FXYM250 x 4	·	·	Foyer Area	
		VCU 2-10 to 2-13	FXYM250 x 4			Auditorium Area	
		RKS35GVMG	FTKS35DVM			Cleaners' Room	



	FAN COIL UNIT						
Sty	Brand	No.	Model	No.	Model	Location	Remarks
3rd	Daikin						
		VFCU 3-1A	FXYAG3			Technician Room	
		VFCU 3-1B	FXYA32			Water Treatment Room	
		FCU 3-1D	F50/R50			Water Treatment Room	
		FCU 3	FT50			Reprocessing Room	
		VFCU 3-1E	FXYA63			Store	
		FCU-3	R60GV1			Store	
		D)// 10 a 1) //					
		RXMQ9AY1	E000351				
		FXSQ125PVE	E002198				
		FXSQ80PVE	E006141				
		RXMQ8AY1	E000540				
		FXSQ125PVE	E000540 E002179				
		FXAQ40PVE	E002179 E017922				
		FXAQ40PVE FXAQ32PVE	E017922 E003872				
		FAAQ32PVE	E003672				
		RXMQ8AY1	E0005421				
		FXSQ125PVE	E002178				
		FXAQ32PVE	E003093				
		FXAQ25PVE	E028239				
		17010,20112	2020200				
		RXMQ6AVE	E001333				
		FXAQ32PVE	E033846				
		FXSQ40PVE	E001779				
		FXFQ63LUV1	E0225687				
		FCU	FDBG 50 AVE				
		VFCU 3-5 & 3-6	FXYM200				
		VFCU 3-7A	FXYA32				
		VFCU 3-7B	FXYA32				
		VFCU 3-7C & 7D	FXYA32 x 2				
		VFCU 3-7E & 7F	FXYA25 x 2				
		VFCU 3-8A	FXYF80				
		VFCU 3-8B & 3-8C	FXYA32 x 2				
		FCU	FDB 50 KVE				



	FAN COIL UNIT						
Sty	Brand	No.	Model	No.	Model	Location	Remarks
4th	Daikin						
		VFCU 4-1A	FXYF125				
		VFCU 4-1B	FXYF80				
		VFCU 4-1C	FXYF80				
		VFCU 4-2A & 4-2B	FXYM80				
		VFCU 4-2C & 4-2D	FXYM50				
		VFCU 4-3A & 4-3B	FXYF125				
		VFCU 4-4A & 4-4B	FXYF125				
		VFCU 4-5	FXYF125				
		FCU 4-6A & 4-6B	FT 35				
5th	Daikin						
		FCU-E5-1	FXMQ20PAVE			IT	
		FCU-E5-2	FXMQ125PAVE			PFM	
		FCU-E5-3	FXMQ125PAVE			BME	
		FCU-E5-4	FXMQ80PAVE	CU-6-1&2	RXQ10 & RXQ 10		E0111 - 17 /
		FCU-E5-7	FXMQ125PAVE			Purchasing	FCU-L5-IT-1
		FCU-NS-1	FXMQ32PAVE			PFM PFM	FCU-L5-IT-2
		FCU-NS-2 FCU-E5-5	FXMQ32PAVE FXMQ80PAVE				FCU-L5-IT-3 FCU-L5-IT-4
		FCU-E5-5 FCU-E5-6	FXMQ80PAVE			Medical Services	FCU-L5-11-4
		FCU-E5-8	FXMQ125PAVE			IT	
		FCU-E5-9	FXMQ50PAVE			Doctor's room	
		FCU-E5-10	FXMQ80PAVE			Logistic driver area	
		FCU-N5-3	FXMQ20PAVE	CU-6-3&4	RXQ10 & RXQ 12	Medical Services	
		FCU-N5-4	FXMQ25PAVE	00 0 00.		Medical Services	
		FCU-N5-5	FXMQ25PAVE			Medical Services	
		FCU-N5-6	FXMQ25PAVE			Doctor's office	
		FCU-N5-8	FXMQ63PAVE			Logistic work area	
		FCU-E5-5A	FXMQ80PAVE	CU-7-5	RXQ16AMYM	Lift Lobby & Service Lobby	
6th	Daikin						
		FCU-E6-8	FXMQ125PAVE			Pantry	
		FCU-N6-4	FXMQ40PAVE	AVE AVE AVE		Meeting room 6A	
		FCU-N6-5	FXMQ40PAVE			Meeting room 6B	
		FCU-N6-6	FXMQ63PAVE		RXQ10 & RXQ 10	Meeting room 6C	
		FCU-E6-9	9 FXMQ80PAVE	ου-υ-πα 4	KAQ10 & KAQ10	Lobby	
		FCU-E6-7	FXMQ20PAVE			Nursing room	
		FCU-N6-2	FXMQ32PAVE			Meeting room 6D	
		FCU-N6-3	FXMQ25PAVE			Director	



	FAN COIL UNIT						
Sty	Brand	No.	Model	No.	Model	Location	Remarks
		FCU-N6-1	FXMQ25PAVE			Director	
		FCU-E6-3	FXMQ80PAVE	1	RXQ10 & RXQ 10	CQ10 & RXQ 10 Office area	
		FCU-E6-2	FXMQ80PAVE				
		FCU-E6-1	FXMQ80PAVE	CU-6-1&2			
		FCU-E6-5	FXMQ80PAVE				
		FCU-E6-6	FXMQ125PAVE				
		FCU-E6-4	FXMQ125PAVE				
		FCU-LAN-1	FTKS50VGM	CU-LAN-1		Riser	
		FCU-LAN-2	FTKS50VGM	CU-LAN-2		Riser	
		FCU-N6-7	FXMQ50PAVE	CU-7-5	RXMQ4AVE	Pantry	
		FCU-E6-5B	FXMQ80PAVE	CU-7-5	RXQ16AMYM	Lift Lobby & Service Lobby	



	FAN COIL UNIT						
Sty	Brand	No.	Model	No.	Model	Location	Remarks
7th	Daikin						
		FCU-N7-1	FXMQ25PAVE			Director Room 2	
		FCU-N7-2	FXMQ25PAVE			Director Room 1	
		FCU-N7-3	FXMQ40PAVE			Finance Room 1	
		FCU-N7-4	FXMQ25PAVE			Director Room 3	
		FCU-N7-5	FXMQ25PAVE			Director Room 4	
		FCU-N7-8	FXMQ20PAVE	CU-7-1&2	RXQ10 + RXQ10	Payroll	
		FCU-N7-9	FXMQ32PAVE			Manager area	
		FCU-E7-1	FXMQ80PAVE			Manager area	
		FCU-E7-2	FXMQ80PAVE			Office area	
		FCU-E7-3	FXMQ80PAVE			Office area	
		FCU-E7-4	FXMQ80PAVE			Storage	
		FCU-N7-6	FXMQ25PAVE			CEO	
		FCU-N7-7	FXMQ25PAVE			Meeting room 7B	
		FCU-E7-5	FXMQ125PAVE			Office area	
		FCU-E7-6	FXMQ20PAVE	CU-7-3&4	RXQ10 + RXQ10	Meeting room 7B	`
		FCU-E7-7	FXMQ80PAVE			Meeting room 7A	
		FCU-E7-8	FXMQ125PAVE			Reception Lobby	
		FCU-E7-9	FXMQ125PAVE			Boardroom	
		FCU-N7-10	FXMQ50PAVE	CU-7-5	RXMQ4AVE	Pantry	
		FCU-E7-5C	FXMQ80PAVE	CU-7-5	RXQ16AMYM	Lift Lobby & Service Lobby	
8th	Daikin						
						Lift Lobby & Service Lobby AHPC/ OOB, SNB	
		VFCU 8-4B	FXYF125			& SCS	
Otle	Dailein						
9th	Daikin					L'ét lables à Comière Lables TOMPR à ORG	
		\/F0H 0 4D	EV//E405			Lift Lobby & Service Lobby TCMPB & SPC &	
		VFCU 9-4B	FXYF125			SDC	
10th	Daikin						
IUth	Daikin	VECIL 40, 44, 9, 40, 45	EVVE405			Lift Labour 9 Comica Labour CMC	
\vdash		VFCU 10-4A & 10-4B	FXYF125			Lift Lobby & Service Lobby SMC	
11th	Daikin						
riui	Daikiii	VFCU 11-4B	FXYM80			Lift Lobby 9 Comice Lobby ICCT	
\vdash		VFCU 11-4B	FAYIVIÖÜ			Lift Lobby & Service Lobby JCST	
12th	Daikin						
1201	Daikiii	VFCU 12-2B	FXYM80			Lift Lobby & Service Lobby AMC	
		VFGU 12-2B	LV I INION			LIII LODDY & Service LODDY AIVIC	